Appl. No. 10/665,910 Amdt. dated July 13, 2006 Amendment under 37 CFR 1.116 Expedited Procedure Examining Group 1773

## Amendments to the Specification:

Please replace paragraph [0006] with the following amended paragraph:

[0006] However, such magnetic head could not be obtained by using any known material based on a even with the reported CoNiFe [[alloy]] material we could not stably make a luster film with enough thickness by electroplating, because of white turbidity, bumps of the film surface. Also, any material based on a Co-Fe two element series alloy is poor in did not have corrosion resistance.